


Memorandum  
Page 2  
July 2, 1991

**Based on plant records, there should not be any PCB items remaining in service at the plant as of July 1, 1991.**

However, please keep in mind that fluorescent light ballasts in the plant may contain small quantities (approximately 1 to 1-1/2 ounces) of PCB fluid in the capacitor itself. If the ballast fails, the capacitor may break open allowing the PCB oil to drip out of the fixture.

If there are any questions concerning the above, feel free to contact me (extension 350).

  
J. A. Selnekovic

JAS/pcb

MPM000829

EPA005250